Steelcase Virtual PUCK Client for Windows

Software Release Notes

12 March, 2018

3.2.0 (release)

Overview

- This update adds audio support to Virtual Puck Client for Windows
- Local machine administrator privileges are required for installation.
- Requires VP Receiver update v3.2.0

Updates

- Added audio support.
- Minimized user interface (supports snap to edge)

Known Issues

- A reboot may be required to complete installation of the virtual audio driver.
- If the virtual audio driver does not install successfully the first time, uninstall the software, reboot the computer and re-install the software.
- Occasionally, Windows may not switch to the correct sound drivers automatically. The audio playback device can be manually switched via the "Playback Devices" control panel within Windows 7 or 10.

Technical Support

Downloads & Documentation
http://techsupport.steelcase.com

Software Update Email Notifications
http://info.steelcase.com/technologyproductsregistry

USA & Canada
Monday–Friday, 8:00am to 8:00pm Eastern Standard Time

Phone 888.783.3522 (English and Spanish)

Email techsupport@steelcase.com

EMEA
Monday–Friday, 8:00 to 18:00 Central European Time

Phone 00800 2000 4000   DACH, France, Benelux, UK and Ireland (English, French and German)
+49 8031 405 111   all other EMEA countries (English, French and German)

Email lineone-en@steelcase.com

APAC
Monday–Friday, 8:00 to 17:00 KL time

Phone +60 3 2027 6161 (Support available in English and Mandarin)

Email apac.techsupport@steelcase.com